



March Q^r 1701

Henry Silvester

A bill of ironeworks from y^e first January 1700 to last of March
Edgar 1701

Longbranch	New irone	
Jersey	Spikes	811
Greenwich	Linspins	345 P
Expedition	Forlocks	403 P
Yorke	{ 40d n 30d n 20d n 10d n	1150
Dunkirk		1159
Phoenix		1200
		500
Bredah	ffor supply of the stores	500 ✓
Cambridge	fforlockeyes	
Nassau	{ Ladel hooks ffo shooeing of hand croulevers	200 P ✓
Lancaster		100 P ✓
Gosport		200 at

P = pair

	C ^t	Q ^r	lb
Poys	96	1	21
Poys	07	3	3
Poys	02	01	0

Nayls for linings

Poiz: means 'after' but is used prior to introducing a quantity by weight.

each